

### Republic of the Philippines SOCIAL SECURITY SYSTEM East Avenue, Diliman, Quezon City

### SEALED QUOTATION FORM

2020-0170

 November 6, 2020
 PHILGEPS BID ID NO.: 86497

 Date
 DATE POSTED
 : 11-06-20

 POSTED BY
 : ERIKA

Sir / Madam:

Please furnish us with your quotation on or before November 10, 2020 @ 5:00PM for the following iter

No.	Quantity	PARTICULARS			Tot	al Cost
		Purchase of Parts and Materials including engine oils and filters Services / Spare Parts / Repair / Replacement for Various Motor N				
		<u>ITEMS</u>	<u>ABC</u>	<u>UoM</u>		
1	1 LOT	Filters & Engine Oils (Hyundai) One (1) unit 2015 Hyundai Starex Gold A/T	₱10,600.00	/lot	P	/lot
2	1 LOT	Filters & Engine Oils (Toyota) One (1) unit 2000 Toyota Revo 1.8L Gas One (1) unit 2000 Toyota Corolla 1.3 One (1) unit 2009 Toyota Hi-Ace Grandia GL One (1) unit 2010 Toyota Fortuner G 2.5 DSL A/T 4x2 One (1) unit 1995 Toyota Hi-Ace Commuter 2.5L	₱34,240.00	/lot	P	/lot
3	1 LOT	Filters & Engine Oils (Isuzu) Four (4) units 2014 Isuzu Crosswind XL One (1) unit 2000 Isuzu Van Truck One (1) unit 2014 Isuzu Dmax Single Cab and Chasis (Pick-up)	₱41,900.00	/lot	P	/lot
4	1 LOT	Filters & Engine Oils (Mitsubishi) Four (4) units 2009 Mitsubishi Adventure One (1) unit 2012 Mitsubishi Montero Sport GTV A/T	₱44,250.00	/lot	P	/lot
5	1 LOT	Spare Parts & Materials (Hyundai) One (1) unit 2015 Hyundai Starex Gold A/T	₱42,660.00	/lot	P	/lot
6	1 LOT	Spare Parts & Materials (Mitsubishi) Fourteen (14) units 2006 & 2009 Mitsubishi Adventure One (1) unit 2012 Mitsubishi Montero Sport GTV A/T	₱420,894.00	/lot	P	/lot
7	1 LOT	Spare Parts & Materials (Toyota) One (1) unit 2000 Toyota Revo 1.8L Gas One (1) unit 2000 Toyota Corolla 1.3 One (1) unit 2009 Toyota Hi-Ace Grandia GL One (1) unit 2010 Toyota Fortuner G 2.5 DSL A/T 4x2 One (1) unit 1995 Toyota Hi-Ace Commuter 2.5L	₱102,229.00	/lot	P	/lot
		(Please accomplish attached Bill of Quantities)				
		GRAND TOTAL ABC = P696,773.00 2020 APP no. 398 - MRTE-Spare Parts/Repairs (Engineering at EFMD - Memo with JO no. 1228-20 received by PPMD on 11/0	5/20 with Requ		t)	

Delivery Terms: Items shall be delivered on or before December 10, 2020

Payment Terms: Government Terms (Payment is upon delivery of items / services &

submission of billing documents.)

Price validity : Three (3) Months

NOTE/S: 1.) For canvass with an ABC of P 100,000.00 and above, the winning bidder is required to post a

Performance Bond from receipt of Notice of Award equivalent to 5% Cash (Goods & Consulting Services) & 10% Cash (Infrastructure), Cashier's / Manager's Check, Bank Guarantee / Draft or 30% Surety Bond callable upon demand, of the contract price.

- 2.) Supplier is required to indicate his PhilGeps Registration Number on the canvass form.
- 3.) SSS shall withhold the applicable taxes from the amount payable in accordance with the BIR regulations.
- 4.) Alternative offer is not allowed.
- 5.) Quantity is subject to change but not to exceed of the approved P.O.
- 6.) Awarding is per lot basis.
- 7.) For further clarifications, you may contact Mr. Ricardo De Guzman/Ms. Vicenta Garnica @ 8920-6401 local 5520 or email at deguzmanid@sss.gov.ph/garnicavl@sss.gov.ph
- 8.) Please submit the accomplished Request for Quotation (RFQ) Form before the closing date at PPMD 2nd flr. SSS Main Bldg., East Ave., Quezon City.Submit in Sealed Envelope address to Ms. VIOLETA V. JAVAR – Corporate Executive Officer IV, Procurement Planning & Management Department and indicate the RFQ Form number, company name, name of company representative, business address and contact details.

This is to certify that my Company is updated in the payment of contributions and loans to SSS, and conformed with the above terms & conditions, and the data / quotation indicated are valid.

Owner/Company Representative	
(Sign over Printed Name)	

Reminder: Price quotation should be made with extra care taking into account the specification and unit of quantity to avoid errors. The offeror binds himself to this quotation.

Please indicate below your	r Business Name,
Address and Telephone Nu	
Your Business SSS No.	
PhilGeps Registration No.	
TIN no.	
Date Received :	
	(Business Name)
(A	ddress & Telephone No.)
	(E-mail Address)

VIOLETAV. JAVAR

Corporate Executive Officer IV ocurement Planning & Management De

Very Truly Yours,

Procurement Planning & Management Department Tel No. 8920-6401 loc 5504-5507/5549 Fax No. 7435-9861

 $\hbox{E-mail Address: bansilea@sss.gov.ph; ppmd@sss.gov.ph}$ 

# FILTERS & ENGINE OILS FOR THE PREVENTIVE MAINTENANCE SERVICE OF 1 UNIT HYUNDAI STAREX GOLD A/T

LOT I	PARTICULAR/PARTS	QTY.	UNIT		PRICE/PC & LITER	TOTAL PRICE
1	MODEL: 2015 HYUNDAI STAREX GOLD A/T CHASIS NO. KMJWA37KBFU745110					
over 1 ft	ENGINE NO.					1-
	OIL FILTER	1	PC.	Php		
1:02	FUEL FILTER	1	PC.			
1:03	AIR FILTER	1	PC.			
1:04	A/C FILTER	1	PC.			
1:05	DIESEL ENGINE OIL (FULLY SYNTHETIC)	8	LITERS			
				Php-	TOTAL	

NOTE: PARTS MUST BE ORIGINAL

## FILTERS & ENGINE OILS FOR THE

PREVENTIVE MAINTENANCE SERVICE OF 1 UNIT TOYOTA REVO,1 UNIT TOYOTA COROLLA,1 UNIT TOYOTA HI-ACE GRANDIA GL, 1 UNIT TOYOTA FORTUNER G 2.5 DSL A/T AND 1 UNIT TOYOTA HI-ACE COMMUTER 2.5L

OT	I	PARTICULAR/PARTS	QTY.	UNIT		PRICE/PC & LITER	TOTAL PRICE
		MODEL: 2000 TOYOTA REVO 1.8L GAS					
1	- 1	CHASIS NO. KF80-8010754					
Barrio I		ENGINE NO.					10
	1:01	OIL FILTER	1	PC.	Php		
-		FUEL FILTER	1	PC.			
$\dashv$		AIR FILTER	1	PC.			
-		GAS ENGINE OIL (FULLY SYNTHETIC)	4	LITERS			
	1.04	SUB-TOTAL			Php		
		MODEL: 2000 TOYOTA COROLLA 1.3					
	2	CHASIS NO. EE110-8008619					
•	•	ENGINE NO.					
	2:01	OIL FILTER	1	PC.	Php		
		FUEL FILTER	1	PC.			
_		AIR FILTER	1	PC.			
(a)		SPARK PLUG	4	PC.			
		GAS ENGINE OIL (FULLY SYNTHETIC)	4	LITERS			
442 - 1	2.00	SUB-TOTAL			Php		
	3	MODEL: 2009 TOYOTA HI-ACE GRANDIA GL CHASIS NO. JTFRS13P600016050 ENGINE NO.					
	3:01	OIL FILTER	1	PC.	Php		
		FUEL FILTER	1	PC.			
-QX 7 9		AIR FILTER	1	PC.		1	
_		A/C FILTER	1	PC.			
		DIESEL ENGINE OIL (FULLY SYNTHETIC)	6	LITERS			
	0.00	SUB-TOTAL			Php		
		MODEL: 2010 TOYOTA FORTUNER G 2.5 DSL	A/T 4X2				
	4	CHASIS NO. MROZR69G500015899					
1617 E	7	ENGINE NO.					
	4:0:	1 OIL FILTER	1	PC.	Php		
		2 FUEL FILTER	1	PC.			
		3 AIR FILTER	1	PC.			
	7.0		1	PC.			
	4.0						
		4 A/C FILTER 5 DIESEL ENGINE OIL (FULLY SYNTHETIC)	7	LITERS			1

		MODEL: 1995 TOYOTA HI-ACE COMMUTER 2.5L				
		CHASIS NO. LH104-0006717				
		ENGINE NO.				
	5:01	OIL FILTER	1	PC.	Php	
NB 08	5:02	FUEL FILTER	1	PC.		
		AIR FILTER	1	PC.		
		DIESEL ENGINE OIL (FULLY SYNTHETIC)	6	LITERS		
	0.2	SUB-TOTAL			Php -	
		TOTAL			Php	

FILTERS & ENGINE OILS FOR THE
PREVENTIVE MAINTENANCE SERVICE OF 4 UNITS ISUZU CROSWIND, 1 UNIT ISUZU PICK-UPDMAX AND 1
UNIT ISUZU VAN (TRUCK)

OT I	PARTICULAR/PARTS	QTY.	UNIT	2.7	PRICE/PC & LITER	TOTAL PRICE
	MODEL: 2014 ISUZU CROSSWIND XL					
1	CHASIS NO. PABTBR54FD2077846					
	ENGINE NO.					
1:01	OIL FILTER	4	PCS.	Php		
1:02	FUEL FILTER	4	PCS.			
1:03	AIR FILTER	4	PCS.		***	
1:04	DIESEL ENGINE OIL ( FULLY SYNTHETIC	24	LITERS			
	SUB-TOTAL.			Php		
	MODEL: 2000 ISUZU VAN (truck)				h	
2	CHASIS NO. PABNHR55ELY-200434					
	ENGINE NO.					
2:01	OILFILTER	1	PC.	Php	יעו	
2:02	FUEL FILTER	1	PC.			
2:03	AIR FILTER	1	PC.			
2:04	DIESEL ENGINE OIL (FULLY SYNTHETIC	7	LITERS			
	SUB-TOTAL					
	MODEL: 2014 ISUZU DMAX SNGLE CAB AND C	HASIS (PI	CK UP)			
3	CHASIS NO. PABTFR86HE2000086					
	ENGINE NO.					
3:01	OIL FILTER	1	PC.	Php		
0.0		1	PC.			
	FUEL FILTER PRIMARY					
3:02	FUEL FILTER PRIMARY  FUEL FILTER SECONDARY	1	PC.			
3:02 3:03 3:04	FUEL FILTER SECONDARY  AIR FILTER	1 1	PC.			
3:02 3:03 3:04	FUEL FILTER SECONDARY  AIR FILTER  DIESEL ENGINE OIL (FULLY SYNTHETIC					
3:02 3:03 3:04	FUEL FILTER SECONDARY  AIR FILTER	1	PC.	Pho		

## FILTERS & ENGINE OILS FOR THE

\*PREVENTIVE MAINTENANCE SERVICE OF 4 UNITS MITSUBISHI ADVENTURE AND 1 UNIT MITSUBISHI MONTERO SPORT GTV A/T

LOT IV	PARTICULAR/PARTS	QTY.	UNIT		PRICE/PC & LITER	TOTAL PRICE
	MODEL: 2009 MITSUBISHI ADVENTURE					
1	CHASIS NO. PAEVB5NJ19BO14796					
	ENGINE NO.					
1:01	OIL FILTER	4	PCS.	Php		
1:02	FUEL FILTER	4	PCS.			
1:03	AIR FILTER	4	PCS.			
1:04	DIESEL ENGINE OIL ( FULLY SYNTHETIC	24	LITERS			
				Php	SUB-TOTAL	

	MÓDEL: 2012 MITSUBISHI MONTERO SPORT C	∋TV		İ	- New York
2	CHASIS NO. MMBGYKH40CFO11914				
	ENGINE NO. 4D56UCDD3679				
2:01	OIL FILTER	1	PC	Php	
2:02	FUEL FILTER	1	PC		
2:03	AIR FILTER	1	PC		
2:04	DIESEL ENGINE OIL (FULLY SYNTHETIC	7	LITERS		
					SUB-TOTAL
				Php	TOTAL

NOTE: PARTS MUST BE ORIGINAL

Sh

	MODEL: 2015 HYUNDAI STAREX GOLD A/T					
LOTY	CHASIS NO. KMJWA37KBFU745110					
AND THE	PLATE NO. ABE-1124					
ITEM NO.	PARTICULAR/PARTS	QTY.	UNIT		PRICE/PC & SET	TOTAL PRICE
1:01	STRUT ASSY, FRONT LH/RH	2	PCS	Php		
1:02	SHOCK ABSORBER REAR LH/RH	2	PCS			
1:03	BALL JOINT ASSY. LOWER ARM LH/RH	2	PCS			
1:04	RACK END LH/RH	2	PCS			
1:05	TIE ROD END ASSY, LH/RH	2	PCS			
1:06	STABILIZER LINK ASSY, FRONT LH/RH	2	PCS			
1:07	STABILIZER LINK ASSY. REAR LH/RH	2	PCS			
14.0	•		TOTAL	Php	1	

NOTE: PARTS MUST BE ORIGINAL

	MODEL: 2006 & 2009 MITSUBIS	HI ADVE	NTURE			
1	CHASIS NO. PAEVB5NJ15 - PAEVB5NJ	119				
	ENGINE NO.					
TEM NO.	PARTICULAR/PARTS	QTY.	UNIT		PRICE/PC	TOTAL PRICE
1:01	SHOCK ABSORBER FRONT	28	PCS	Php		
1:02	SHOCK ABSORBER REAR	28	PCS			
1:03	BALL, JOINT UPPER	28	PCS			
1:04	BALL JOINT LOWER	28	PCS			
1:05	RACK END	28	PCS			
1:06	TIE ROD END	28	PCS			
1:07	CLUTCH DISC	23	PCS			
1:08	CLUTCH COVER	13	PCS			
1:09	RELEASE BEARING	13	PCS			
1:10	PILOT BEARING	13	PCS			
1:11	BACK DOOR STAY	28	PCS			
1:12	LOWER ARM BUSHING	28	PCS			
1:13	UPPER ARM ASSY.	28	PCS			
1:14	BRAKE MASTER ASSY.	14	PCS			
1:15	PRIMARY CLUTCH MASTER ASSY.	14	PCS			
				Php	SUB-TOTAL	

2	MODEL: 2012 MITSUB CHASIS NO. MMBGYKH40CF		TERO S	PORT	GTV A	/T	
_	ENGINE NO. 4D56UCDD3679	9					
ITEM NO.	PARTICULAR/PAR	TS	QTY.	UNIT		PRICE/PC	TOTAL PRICE
2:01	SHOCK ABSORBER FRONT	(ORIG)	2	PCS	Php		
2:02	SHOCK ABSORBER REAR	(ORIG)	2	PCS			
2:03	BALL JOINT UPPER	(ORIG)	2	PCS			
2:04	BALL JOINT LOWER	(ORIG)	2	PCS			
2:05	RACK END	(ORIG)	2	PCS			
2:06	TIE ROD END	(ORIG)	2	PCS			
2:07	BACK DOOR STAY	(ORIG)	2	PCS		1	
-		-1-				SUB-TOTAL	
					Php	TOTAL	

LOT VII

LOT VI										
PG1 1 7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	MODEL: 2000 TOYOTA REVO 1.8L GAS									
1	CHASIS NO. KF80-8010754									
	PLATE NO. : SFK-406									
ГЕМ NO.	PARTICULAR/PARTS	QTY.	UNIT		PRICE/PC & SET	TOTAL PRICE				
1:01	SHOCK ABSORBER FRONT (LEFT & RIGHT)	2	PCS	Php						
1:02	SHOCK ABSORBER REAR (LEFT & RIGHT)	2	PCS							
1:03	BALL JOINT UPPER (LEFT & RIGHT)	2	PCS							
1:04	BALL JOINT LOWER (LEFT & RIGHT)	2	PCS							
1:05	RACK END (LEFT & RIGHT)	2	PCS							
1:06	TIE ROD END (LEFT & RIGHT)	2	PCS							
1:07	CLUTCH DISC	1	PC							
1:08	CLUTCH COVER	1	PC							
1:09	REALEASE BEARING	1	PC							
1:10	PILOT BEARING	1	PC							
1:11	BACK DOOR STAY (LEFT & RIGHT)	2	PCS	1						
1:12	BRAKE MASTER ASSY.	1	PC	+		<u> </u>				
1:13	CLUTCH MASTER PRIMARY ASSY.	1	PC	+	-					
1.13	CLUTCH MASTER FINIVARY ASST.		10	+						
	Ţ			+						
				-						
	SUB-TOTAL			Php		<u> </u>				
	MODEL: 2000 TOYOTA COROLLA 1.3									
2	CHASIS NO. EE110-8008619									
	PLATE NO.: WSD-686				100000000000000000000000000000000000000					
2:01	SHOCK ABSORBER FRONT (LEFT & RIGHT)	2	PCS	Php						
2:02	SHOCK ABSORBER REAR (LEFT & RIGHT)	2	PCS							
2:03	BALL JOINT LOWER (LEFT & RIGHT)	2	PCS							
2:04	RACK END (LEFT & RIGHT)	2	PCS							
2:05	TIE ROD END (LEFT & RIGHT)	2	PCS	1						
2:06	CLUTCH DISC	1	PC	1						
2:07	CLUTCH COVER	1	PC	+						
2:08	REALEASE BEARING	1	PC	+		1				
2:09	BRAKE MASTER ASSY.	1	PC	+		-				
2:10	CLUTCH MASTER PRIMARY ASSY.	1	PC	-		-				
			PC	+	-					
2:11	CLUTCH MASTER SECONDARY ASSY.	1		-	-	-				
2:12	SHOCK MOUNTING FRONT	2	PCS	-		-				
2:13	SHOCK MOUNTING REAR	2	PCS	+	-	-				
	ť			-	<u></u>	-				
	SUB-TOTAL			Php	1					
1	·									
-	MODEL: 2009 TOYOTA HI-ACE GRANDIA GL									
3	·									
3	MODEL: 2009 TOYOTA HI-ACE GRANDIA GL									
3 3:01	MODEL: 2009 TOYOTA HI-ACE GRANDIA GL CHASIS NO. JTFRS13P600016050	1	PC	Php						
	MODEL: 2009 TOYOTA HI-ACE GRANDIA GL CHASIS NO. JTFRS13P600016050 PLATE NO. : SJA-897	1 1	PC PC	Php						
3:01	MODEL: 2009 TOYOTA HI-ACE GRANDIA GL CHASIS NO. JTFRS13P600016050 PLATE NO.: SJA-897 CLUTCH DISC		-	Php						
3:01	MODEL: 2009 TOYOTA HI-ACE GRANDIA GL CHASIS NO. JTFRS13P600016050 PLATE NO.: SJA-897 CLUTCH DISC CLUTCH COVER	1	PC	Php						
3:01 3:02 3:03 3:04	MODEL: 2009 TOYOTA HI-ACE GRANDIA GL CHASIS NO. JTFRS13P600016050 PLATE NO.: SJA-897 CLUTCH DISC CLUTCH COVER REALEASE BEARING PILOT BEARING	1 1	PC PC	Php						
3:01 3:02 3:03 3:04 3:05	MODEL: 2009 TOYOTA HI-ACE GRANDIA GL CHASIS NO. JTFRS13P600016050 PLATE NO.: SJA-897 CLUTCH DISC CLUTCH COVER REALEASE BEARING PILOT BEARING BACK DOOR STAY (LEFT & RIGHT)	1 1 1 2	PC PC PC PCS	Php						
3:01 -3:02 3:03 3:04 3:05 3:06	MODEL: 2009 TOYOTA HI-ACE GRANDIA GL CHASIS NO. JTFRS13P600016050 PLATE NO.: SJA-897 CLUTCH DISC CLUTCH COVER REALEASE BEARING PILOT BEARING BACK DOOR STAY (LEFT & RIGHT) BRAKE MASTER ASSY.	1 1 1 2 1	PC PC PCS PCS	Php						
3:01 3:02 3:03 3:04 3:05	MODEL: 2009 TOYOTA HI-ACE GRANDIA GL CHASIS NO. JTFRS13P600016050 PLATE NO.: SJA-897 CLUTCH DISC CLUTCH COVER REALEASE BEARING PILOT BEARING BACK DOOR STAY (LEFT & RIGHT)	1 1 1 2	PC PC PC PCS	Php						
3:01 -3:02 3:03 3:04 3:05 3:06	MODEL: 2009 TOYOTA HI-ACE GRANDIA GL CHASIS NO. JTFRS13P600016050 PLATE NO.: SJA-897 CLUTCH DISC CLUTCH COVER REALEASE BEARING PILOT BEARING BACK DOOR STAY (LEFT & RIGHT) BRAKE MASTER ASSY.	1 1 1 2 1	PC PC PCS PCS	Php						

[Php ]

	MODEL: 2010 TOYOTA FORTUNER G 2.5 DSL A/T	4X2					
4	CHASIS NO. MROZR69G500015899	( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( ) ( )					
	PLATE NO.: SJX-560						
4:01	BALL JOINT UPPER (LEFT & RIGHT)	2	PCS	Php			
4:02	BALL JOINT LOWER (LEFT & RIGHT)	2	PCS				
4:03	RACK END (LEFT & RIGHT)	2	PCS				1
4:04	TIE ROD END (LEFT & RIGHT)	2	PCS				
4:05	BACK DOOR STAY (LEFT & RIGHT)	2	PCS				
1900	<u></u>	2	PCS				
4:06	SHOCK ABSORBER ASSY, FRONT (ORIG.)	2	PCS				
4:07	SHOCK ABSORBER ASSY: REAR (ORIG.)	2	PCS				
- da	SUB-TOTAL			Php	]		pr n
5	CHASIS NO. LH104-0006717 PLATE NO.: SEF-321						
	I DITE NO.: OEI OEI						
5:01	SHOCK ABSORBER FRONT (LEFT & RIGHT)	2	PCS	Php			
5:01 5:02		2	PCS PCS	Php			
	SHOCK ABSORBER FRONT (LEFT & RIGHT)			Php			
5:02	SHOCK ABSORBER FRONT (LEFT & RIGHT) SHOCK ABSORBER REAR (LEFT & RIGHT)	2	PCS	Php			
5:02 5:03	SHOCK ABSORBER FRONT (LEFT & RIGHT) SHOCK ABSORBER REAR (LEFT & RIGHT) BALL JOINT UPPER (LEFT & RIGHT) ASSY.	2	PCS PCS	Php			
5:02 5:03 5:04	SHOCK ABSORBER FRONT (LEFT & RIGHT) SHOCK ABSORBER REAR (LEFT & RIGHT) BALL JOINT UPPER (LEFT & RIGHT) ASSY. BALL JOINT LOWER (LEFT & RIGHT)	2 2 2	PCS PCS PCS	Php	and the second		
5:02 5:03 5:04 5:05	SHOCK ABSORBER FRONT (LEFT & RIGHT) SHOCK ABSORBER REAR (LEFT & RIGHT) BALL JOINT UPPER (LEFT & RIGHT) ASSY. BALL JOINT LOWER (LEFT & RIGHT) RACK END (LEFT & RIGHT)	2 2 2 2	PCS PCS PCS	Php			
5:02 5:03 5:04 5:05 5:06	SHOCK ABSORBER FRONT (LEFT & RIGHT) SHOCK ABSORBER REAR (LEFT & RIGHT) BALL JOINT UPPER (LEFT & RIGHT) ASSY. BALL JOINT LOWER (LEFT & RIGHT) RACK END (LEFT & RIGHT) TIE ROD END (LEFT & RIGHT)	2 2 2 2 2	PCS PCS PCS PCS	Php			
5:02 5:03 5:04 5:05 5:06 5:07	SHOCK ABSORBER FRONT (LEFT & RIGHT) SHOCK ABSORBER REAR (LEFT & RIGHT) BALL JOINT UPPER (LEFT & RIGHT) ASSY. BALL JOINT LOWER (LEFT & RIGHT) RACK END (LEFT & RIGHT) TIE ROD END (LEFT & RIGHT) CLUTCH DISC	2 2 2 2 2 1	PCS PCS PCS PCS PCS	Php			
5:02 5:03 5:04 5:05 5:06 5:07 5:08	SHOCK ABSORBER FRONT (LEFT & RIGHT) SHOCK ABSORBER REAR (LEFT & RIGHT) BALL JOINT UPPER (LEFT & RIGHT) ASSY. BALL JOINT LOWER (LEFT & RIGHT) RACK END (LEFT & RIGHT) TIE ROD END (LEFT & RIGHT) CLUTCH DISC CLUTCH COVER	2 2 2 2 2 2 1	PCS PCS PCS PCS PCS PCS PCS	Php			
5:02 5:03 5:04 5:05 5:06 5:07 5:08 5:09	SHOCK ABSORBER FRONT (LEFT & RIGHT) SHOCK ABSORBER REAR (LEFT & RIGHT) BALL JOINT UPPER (LEFT & RIGHT) ASSY. BALL JOINT LOWER (LEFT & RIGHT) RACK END (LEFT & RIGHT) TIE ROD END (LEFT & RIGHT) CLUTCH DISC CLUTCH COVER REALEASE BEARING	2 2 2 2 2 1 1 1	PCS PCS PCS PCS PCS PCS PCS PC	Php			
5:02 5:03 5:04 5:05 5:06 5:07 5:08 5:09 5:10	SHOCK ABSORBER FRONT (LEFT & RIGHT) SHOCK ABSORBER REAR (LEFT & RIGHT) BALL JOINT UPPER (LEFT & RIGHT) ASSY. BALL JOINT LOWER (LEFT & RIGHT) RACK END (LEFT & RIGHT) TIE ROD END (LEFT & RIGHT) CLUTCH DISC CLUTCH COVER REALEASE BEARING PILOT BEARING	2 2 2 2 2 1 1 1 1	PCS PCS PCS PCS PCS PC PC PC	Php			
5:02 5:03 5:04 5:05 5:06 5:07 5:08 5:09 5:10	SHOCK ABSORBER FRONT (LEFT & RIGHT) SHOCK ABSORBER REAR (LEFT & RIGHT) BALL JOINT UPPER (LEFT & RIGHT) ASSY. BALL JOINT LOWER (LEFT & RIGHT) RACK END (LEFT & RIGHT) TIE ROD END (LEFT & RIGHT) CLUTCH DISC CLUTCH COVER REALEASE BEARING PILOT BEARING BRAKE MASTER ASSY.	2 2 2 2 2 1 1 1 1	PCS PCS PCS PCS PCS PC PC PC PC	Php			
5:02 5:03 5:04 5:05 5:06 5:07 5:08 5:09 5:10 5:11	SHOCK ABSORBER FRONT (LEFT & RIGHT) SHOCK ABSORBER REAR (LEFT & RIGHT) BALL JOINT UPPER (LEFT & RIGHT) ASSY. BALL JOINT LOWER (LEFT & RIGHT) RACK END (LEFT & RIGHT) TIE ROD END (LEFT & RIGHT) CLUTCH DISC CLUTCH COVER REALEASE BEARING PILOT BEARING BRAKE MASTER ASSY. CLUTCH MASTER PRIMARY ASSY.	2 2 2 2 2 1 1 1 1 1	PCS PCS PCS PCS PCS PC PC PC PC PC	Php			
5:02 5:03 5:04 5:05 5:06 5:07 5:08 5:09 5:10 5:11 5:12	SHOCK ABSORBER FRONT (LEFT & RIGHT) SHOCK ABSORBER REAR (LEFT & RIGHT) BALL JOINT UPPER (LEFT & RIGHT) ASSY. BALL JOINT LOWER (LEFT & RIGHT) RACK END (LEFT & RIGHT) TIE ROD END (LEFT & RIGHT) CLUTCH DISC CLUTCH COVER REALEASE BEARING PILOT BEARING BRAKE MASTER ASSY. CLUTCH MASTER PRIMARY ASSY.	2 2 2 2 1 1 1 1 1 1 1 1 1 2	PCS PCS PCS PCS PCS PC PC PC PC PC PC PC PC				

Note: OTHER PARTS MUST BE A1 REPLACEMENT

