

PROJECT:           STAIR PRESSURIZATION SYSTEM

REPLY TO WRITTEN QUERIES:

	Query/Clarifications	TWG/BAC Reply
1	Tapping point/location of power supply for the pressurization blowers.	Tapping point of power supply for the pressurization blowers will be at the basement area, Electrical Room of SSS Main Building.
2	FDAS tapping point/location of pressurization blower, controls should be Normally Open Dry Contact.	Tapping point of FDAS will be at the basement area, Control Room of SSS Main Building. Tapping point is normally open, dry contact
3	Can you send us floor plans of tapping point/ locations.	Please see Annex B